



CONSTRUCTION  
INDUSTRY COUNCIL  
建造業議會

# Painter and Decorator (Paperhanging) Trade Test Mock Written Test Paper

此文件關於髹漆及裝飾工（裱貼牆紙）工藝測試考題有需要索取此文件的中文版本，請致電 2100 9000 與香港建造業工藝測試中心聯絡。

## **Disclaimer**

*No part of this material may be reproduced or transmitted in any form or any means without the written permission of the CIC. Whilst reasonable efforts have been made to ensure the accuracy of the information contained in this material, the CIC nevertheless would encourage readers to seek appropriate independent advice from their professional advisers where possible and readers should not treat or rely on this material as a substitute for such professional advice for taking any relevant actions.*

## **Enquiries**

Enquiries on this Material may be made to the Hong Kong Construction Industry Trade Testing Centre at:

95, Yue Kwong Road  
Aberdeen  
Hong Kong

Tel: (852) 2100 9000  
Fax: (852) 2100 9090  
Email: [enquiry@cic.hk](mailto:enquiry@cic.hk)  
Website: [www.cic.hk](http://www.cic.hk)

© 2020 Construction Industry Council.

1. Fences should be set for the areas that can cause humans falling from heights. Its height must not be less than
  - a. 300mm
  - b. 600mm
  - c. 900mm
  - d. 1200mm
  
2. When is the next re-inspection of an air compressor by the appointed inspector after issuing the Certificate of Fitness?
  - a. Within 6 months
  - b. Within 12 months
  - c. Within 18 months
  - d. Within 26 months
  
3. Which of the following is the reason why workers are required to wear hard hats?
  - a. For the sake of aesthetic
  - b. To resist from wind and rain
  - c. To prevent one's head from getting hurt
  - d. To indicate different ranks of workers
  
4. In terms of Dangerous Goods, the varnish is categorised as
  - a. Dangerous goods No. 3
  - b. Dangerous goods No. 5
  - c. Dangerous goods No. 7
  - d. None of the above
  
5. The main component of gypsum powder that used for filling joints is \_\_\_\_\_
  - a. Calcium carbonate
  - b. Calcium sulphate
  - c. Calcium oxide
  - d. Iron(III) oxide

6. The main component of white limestone powder, which is commonly used in filler, is \_\_\_\_
  - a. Calcium sulphate
  - b. Calcium carbonate
  - c. Calcium oxide
  - d. Aluminium oxide
  
7. Double size that stored for too long will \_\_\_\_
  - a. Dry and vapourise
  - b. Dry and soften
  - c. Rancid and sweat
  - d. Rancid and grease
  
8. While sandpapering the plaster of the wall, which level of wood (red) sandpaper is conventionally used?
  - a. No. 40-50
  - b. No. 100-150
  - c. No. 190-200
  - d. No. 230-240
  
9. The width of a normal rolled wallpaper is around \_\_\_\_\_.
  - a. 485mm (19 inches)
  - b. 535mm (21 inches)
  - c. 585mm (23 inches)
  - d. 635mm (25 inches)
  
10. The length of a normal rolled wallpaper is around \_\_\_\_\_.
  - a. 5m (16.5 feet)
  - b. 10m (33 feet)
  - c. 15m (49.5 feet)
  - d. 20m (66 feet)

11. The paint used on the wall before mouting the wallpaper is usually \_\_\_\_\_.
  - a. Road marking paint
  - b. Zinc Chromate Primer
  - c. Texture base coat
  - d. Varnish
  
12. Which type of wallpaper cannot come into contact with the paste during construction?
  - a. PVC wallpaper
  - b. Metallic wallpaper
  - c. Velvet wallpaper
  - d. None of the above
  
13. Which of the following materials could shorten the drying time of double size filler with varnish mixture by hand at the highest rate ?
  - a. Double size
  - b. Gypsum powder
  - c. White limestone powder
  - d. Varnish
  
14. Which of the following models of wood (red) sandpaper has the largest diameter of sand granules?
  - a. No. 100
  - b. No. 120
  - c. No. 150
  - d. No. 180
  
15. Which of the following materials has the slowest rate of volatilization
  - a. Naphtha
  - b. Turpentine
  - c. Thinner
  - d. Alcohol

16. Which of the following procedures is correct when mounting a wallpaper?
- Mount the wallpaper on the plastered surface that has been applied with varnish
  - Mount the wallpaper on the plastered surface that has been applied with emulsion paint
  - Mount the wallpaper on the plastered surface that has been applied with distemper
  - Mount the wallpaper on the plastered surface that has been applied with lime wash
17. Which of the following width of paint scraper is hard to purchase on the market?
- 1 inches
  - 2 inches
  - 4 inches
  - 7 inches
18. If air bubbles were found after the drying of the wallpaper, what should one do to fix it?
- Change the wallpaper
  - Use a cutter to cut open the air bubbles with no further treatment
  - Use a syringe to inject the paste, and then smooth out the air bubbles
  - Directly use a new wallpaper to cover the areas with air bubbles
19. What is the consequence if there is any act of bribery in the construction industry?
- Lower the quality of the construction
  - Improve business environment
  - Create a fairer tendering
  - Lower the cost of construction
20. In violating the section 9 of the Prevention of Bribery Ordinance, the maximum penalty is \_\_\_\_\_.
- Imprisonment for 10 years
  - Imprisonment for 20 years
  - A fine of \$10,000 and imprisonment for 1 year
  - A fine of \$500,000 and imprisonment for 7 years

- End of Paper -