





GOOD PRACTICES



Employers, contractors and persons in charge of works should, with due regard to the working conditions, conduct risk assessment and formulate and implement appropriate control measures, including provisions for prevention of fall into water.



Employers, contractors and persons in charge of works should provide workers with suitable personal protective equipment and ensure the proper use of them. If there is a risk of fall into water, every worker should wear a suitable lifejacket.



Employers, contractors and persons in charge of works should provide adequate safety training and supervision to the workers.



Personal protective equipment, including lifejacket, should be regularly checked and properly maintained in good serviceable conditions. Lifejackets should be periodically inspected by authorised service agents.



Disclaimer

Whilst reasonable efforts have been made to ensure the accuracy of the information contained in this publication, the CIC nevertheless would encourage readers to seek appropriate independent advice from their professional advisers where possible and readers should not treat or rely on this publication as a substitute for such professional advice for taking any relevant actions.